Test report No. : 11932168H-B-R1
Page : 52 of 54
Issued date : February 26, 2018
FCC ID : VPYLB1NX

## **APPENDIX 3: Photographs of test setup**

## **Conducted Emission**




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 11932168H-B-R1
Page : 53 of 54
Issued date : February 26, 2018
FCC ID : VPYLB1NX

## **Radiated Spurious Emission**




Photo 1




Photo 2


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124


: 11932168H-B-R1 Test report No. Page : 54 of 54 Issued date : February 26, 2018 FCC ID : VPYLB1NX

Worst Case Position
Below 1GHz (Horizontal: Y-axis/ Vertical: Y-axis) Above 1GHz (Horizontal: X-axis/ Vertical: X-axis)






Y-axis



**Z**-axis



**End of Report** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile : +81 596 24 8124