Test report No.
 : 11469126H-A-R1

 Page
 : 69 of 71

 Issued date
 : December 28, 2016

 FCC ID
 : VPYLB1JS955

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 11469126H-A-R1
Page : 70 of 71
Issued date : December 28, 201

Issued date : December 28, 2016 FCC ID : VPYLB1JS955

Radiated Spurious Emission




Photo 1



Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

: 11469126H-A-R1 Test report No. Page : 71 of 71 Issued date : December 28, 2016 FCC ID : VPYLB1JS955


Worst Case Position

WLAN (Horizontal: Z-axis/ Vertical: Y-axis) BT LE (Horizontal: X-axis/ Vertical: Y-axis)


X-axis



Y-axis



Z-axis



End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile : +81 596 24 8124