Test report No. : 10103823H-R1 : 53 of 56 Page FCC ID : VPYLBYR650 Issued date : October 28, 2013 Revised date : October 30, 2013

## **APPENDIX 4: Photographs of test setup**

## 1. Photographs of EUT

Top



Bottom



Front



Rear



Left Side



Right side




4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 10103823H-R1
Page : 54 of 56
FCC ID : VPYLBYR650
Issued date : October 28, 2013
Revised date : October 30, 2013

## 2. Antenna position




4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 10103823H-R1 Page : 55 of 56 FCC ID : VPYLBYR650 **Issued date** : October 28, 2013 : October 30, 2013 Revised date

## 3. Photographs of setup






4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN Telephone: +81 596 24 8999

Facsimile: +81 596 24 8124

Test report No. : 10103823H-R1Page : 56 of 56 FCC ID : VPYLBYR650 **Issued date** : October 28, 2013 Revised date : October 30, 2013



**End of Report** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124