Test report No. : 12717687H-A-R1 : 59 of 61 : July 1, 2019 : VPYLB1KS Page Issued date FCC ID

## **APPENDIX 3: Photographs of test setup**

## **Conducted Emission**




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 12717687H-A-R1
Page : 60 of 61
Issued date : July 1, 2019
FCC ID : VPYLB1KS

## **Radiated Spurious Emission**




Photo 1





Photo 2


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 12717687H-A-R1
Page : 61 of 61
Issued date : July 1, 2019
FCC ID : VPYLB1KS

## Worst Case Position (Horizontal: Y-axis/ Vertical: Z-axis)







**End of Report** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124