Test report No. : 10300021H-A
Page : 33 of 37
Issued date : May 23, 2014
FCC ID : VPYLBZF

#### **APPENDIX 3: Photographs of test setup**

#### **Conducted Emission**

(Model No.: ZF)



Photo 1




Photo 2

#### UL Japan, Inc. Ise HQ EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10300021H-A Page : 34 of 37 : May 23, 2014 : VPYLBZF Issued date FCC ID

## Conducted Emission (Model No.: ZW)



Photo 1




Photo 2

### UL Japan, Inc. Ise HQ EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10300021H-A Page : 35 of 37 : May 23, 2014 : VPYLBZF Issued date FCC ID

## Radiated Spurious Emission (Model No.: ZF)



Photo 1




Photo 2

### UL Japan, Inc. Ise HQ EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10300021H-A Page : 36 of 37 Issued date FCC ID : May 23, 2014 : VPYLBZF

# Radiated Spurious Emission (Model No.: ZW)



Photo 1




Photo 2

#### UL Japan, Inc. Ise HQ EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10300021H-A
Page : 37 of 37
Issued date : May 23, 2014
FCC ID : VPYLBZF


### **Worst Case Position**

Above 1GHz (Horizontal: Y-axis/ Vertical:Z-axis) Below 1GHz (Horizontal: X-axis/ Vertical:X-axis)






Y-axis



**Z**-axis



**End of Report** 

#### UL Japan, Inc. Ise HQ EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124