Test report No.
 : 11255696H-A

 Page
 : 29 of 30

 Issued date
 : May 20, 2016

 FCC ID
 : VPYLBYD

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1



Photo 2

UL Japan, Inc. Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 11255696H-A
Page : 30 of 30
Issued date : May 20, 2016
FCC ID : VPYLBYD

Worst Case Position

(Horizontal: X0-axis / Vertical: Z0-axis) (Below 1 GHz) (Horizontal: Y90-axis / Vertical: Z0-axis) (Above 1 GHz)



End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124