Test report No. : 11197179H-A-R2
Page : 35 of 38
Issued date : July 7, 2016
FCC ID : VPYLB1EU

APPENDIX 3: Photographs of test setup

Conducted Emission



Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 11197179H-A-R2
Page : 36 of 38
Issued date : July 7, 2016
FCC ID : VPYLB1EU

Radiated Spurious Emission




Photo 1





Photo 2


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Test report No. : 11197179H-A-R2
Page : 37 of 38
Issued date : July 7, 2016
FCC ID : VPYLB1EU


<u>Worst Case Position</u> Antenna (Horizontal: Y90-axis/ Vertical: X90-axis)












4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Test report No. : 11197179H-A-R2
Page : 38 of 38
Issued date : July 7, 2016
FCC ID : VPYLB1EU

<u>Worst Case Position</u> Module (Horizontal: X-axis/ Vertical: X-axis)






Y-axis



Z-axis



End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN