Test report No. : 10689818H-C-R1
Page : 141 of 147
Issued date : June 17, 2015
Revised date : June 22, 2015
FCC ID : VPYLB1EN

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1



Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10689818H-C-R1
Page : 142 of 147
Issued date : June 17, 2015
Revised date : June 22, 2015
FCC ID : VPYLB1EN

Radiated Spurious Emission




Photo 1



Photo 2


UL Japan, Inc. Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Test report No. : 10689818H-C-R1
Page : 143 of 147
Issued date : June 17, 2015
Revised date : June 22, 2015
FCC ID : VPYLB1EN

Worst Case Position (Antenna: SISO)


(Horizontal: Z1(90deg) / Vertical: X1(90deg)) (Above 1GHz) (Horizontal: X1(0deg)/ Vertical: X1(0deg)) (Below 1GHz)















UL Japan, Inc. Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Test report No. : 10689818H-C-R1
Page : 144 of 147
Issued date : June 17, 2015
Revised date : June 22, 2015
FCC ID : VPYLB1EN














UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10689818H-C-R1
Page : 145 of 147
Issued date : June 17, 2015
Revised date : June 22, 2015
FCC ID : VPYLB1EN

Worst Case Position (Antenna: MIMO)

(Horizontal: Z1(90deg) / Vertical:X1(90deg)) (Above 1GHz)





UL Japan, Inc. Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10689818H-C-R1
Page : 146 of 147
Issued date : June 17, 2015
Revised date : June 22, 2015
FCC ID : VPYLB1EN














UL Japan, Inc. Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10689818H-C-R1
Page : 147 of 147
Issued date : June 17, 2015
Revised date : June 22, 2015
FCC ID : VPYLB1EN


Worst Case Position (Module)

(Horizontal: X-axis/ Vertical: X-axis)


X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN