: 11212787H-A-R1 Test report No. Page : 50 of 52 : September 27, 2016 : VPYLB1JP Issued date

FCC ID

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 11212787H-A-R1
Page : 51 of 52

Issued date : September 27, 2016 FCC ID : VPYLB1JP

Radiated Spurious Emission




Photo 1




Photo 2


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124


Test report No. : 11212787H-A-R1
Page : 52 of 52
Issued date : September 27, 2016
FCC ID : VPYLB1JP

Worst Case Position

(Horizontal: X-axis / Vertical: Y-axis) (Above 1GHz) (Horizontal: X-axis / Vertical: X-axis) (Below 1GHz)







End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124