Test report No. : 31KE0354-HO-01-A

Page : 12 of 48
Issued date : July 26, 2011
FCC ID : VPYLBTN

## **APPENDIX 1: Photographs of test setup**

## **Conducted Emission**



Photo 1



Photo 2

# UL Japan, Inc.

### **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 31KE0354-HO-01-A

Page : 13 of 48
Issued date : July 26, 2011
FCC ID : VPYLBTN

## **Radiated Spurious Emission**



Photo 1



Photo 2

# UL Japan, Inc.

### **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 31KE0354-HO-01-A

Page : 14 of 48
Issued date : July 26, 2011
FCC ID : VPYLBTN


## **Worst Case Position**

Below 1GHz: Horizontal: X-axis/ Vertical: X-axis Above 1GHz: Horizontal: X-axis/ Vertical: Z-axis


## X-axis



Y-axis



**Z**-axis



## UL Japan, Inc.

**Head Office EMC Lab.** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124