


 Prüfbericht - Nr.:
 15093884 001
 Seite 1 von 2

 Test Report No.
 Page 1 of 2

## **Appendix II- Photographs of the Test Set-Up**

Photograph 1: Set-up for Conducted RF test at Antenna Port







Prüfbericht - Nr.: 15093884 001

Test Report No.

Seite 2 von 2
Page 2 of 2

Photograph 2: Set-up for Spurious Emissions below 1GHz



