Test report No.
 : 13004393S-E-R2

 Page
 : 376 of 379


 Issued date
 : December 23, 2019

 FCC ID
 : VPYLB1VY

APPENDIX 3: Photographs of test setup

Conducted Emission






UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Test report No. : 13004393S-E-R2
Page : 377 of 379
Issued date : December 23, 2019
FCC ID : VPYLB1VY

Radiated Spurious Emission








1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Test report No. : 13004393S-E-R2
Page : 378 of 379
Issued date : December 23, 2019
FCC ID : VPYLB1VY

Pre-check of Worst Case Position

Module








1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Test report No. : 13004393S-E-R2
Page : 379 of 379
Issued date : December 23, 2019
FCC ID : VPYLB1VY

Pre-check of Worst Case Position



End of Report

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN