Test report No. : 12530177H-A-R1
Page : 70 of 71
Issued date : November 5, 2018
FCC ID : VPYLB1JS955

## **APPENDIX 3: Photographs of test setup**

## **Radiated Spurious Emission**




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 12530177H-A-R1
Page : 71 of 71
Issued date : November 5, 2018
FCC ID : VPYLB1JS955


## **Worst Case Position**

Above 1GHz (Horizontal: X-axis/ Vertical: Y-axis) Below 1 GHz (Horizontal: X-axis/ Vertical: Y-axis)


X-axis



Y-axis



**Z**-axis



**End of Report** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124