Page : 107 of 110
Issued date : October 19, 2012
Revised date : October 24, 2012
FCC ID : VPYLBVX532

APPENDIX 3: Photographs of test setup

Conducted Emission



Photo 1




Photo 2

UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Page : 108 of 110
Issued date : October 19, 2012
Revised date : October 24, 2012
FCC ID : VPYLBVX532

Radiated Spurious Emission



Photo 1



Photo 2


UL Japan, Inc.


Head Office EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Page : 109 of 110
Issued date : October 19, 2012
Revised date : October 24, 2012
FCC ID : VPYLBVX532

Worst Case Position (Horizontal: Z-axis/ Vertical: Y-axis) Low power







^{*}The module and antenna will be mounted on a jig board with the same specification as the one used for testing, and it will be installed in the end product.

UL Japan, Inc.

Head Office EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Page : 110 of 110
Issued date : October 19, 2012
Revised date : October 24, 2012
FCC ID : VPYLBVX532

Worst Case Position (Horizontal: X-axis/ Vertical: Z-axis) High power

X-axis







^{*}The module and antenna will be mounted on a jig board with the same specification as the one used for testing, and it will be installed in the end product.

End of Report

UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN