

16-3 Kuramae 4-chome, Taito-ku, Tokyo, 111-0051, Japan Phone: +81-3(3862)6600

FAX: +81-3(3862)5255

To: Federal Communications Commission Equipment Authorization Branch 7435 Oakland Mills Road Columbia, MD 21046

We, GL Solutions Inc., will respond to this issue with below action.

[Issue]

For this FCC ID (VQ7TM10-B-QQ) filing, we have been uploaded the incorrect FCC ID (VQ7TM-B-QQ) label and we had been distributed about 4,000 RF modules with FCC ID (VQ7TM-B-QQ).

[Action]

This issue was consulted with the FCC staff in KDB inquiry with tracker number 245147. In accordance with this consult:

- 1. We will submit the correct FCC ID (VQ7TM10-B-QQ) label to TCB and they will upload the correct label on FCC server.
- 2. We will create another FCC ID (VQ7TM-B-QQ) by means of a Change ID based on the existing FCC ID (VQ7TM10-B-QQ) filing. All devices in the field will then refer to a correct and existing FCC ID again.

Issued Date: October 27, 2014

Issued by: Katsumi Izaki

Signature: K- Izaki