

1. Block diagram:

The 2.402~2,480GHz frequency value of the XTAL shown on block diagram is not correct. 2.402~2,480GHz frequency is for operating frequency, but not the real value of the XTAL. The correct value of XTAL should be 16MHz according to the provided schematics. Please supply revised block diagram with correct frequency value.

The revised Block diagram with correct frequency value has been uploaded to website.

2. Test report:

The antenna photo at page 8 o f 48 is out of focus. Please provide a better photo.

The revised test report with clear antenna photo has been uploaded to website.