November 3, 2007

RE: TWS Digital Technology (Shenzhen) Limited

FCC ID: VQCTWSBSH631101

I have a few comments on this application. Depending on your responses, kindly understand there may be additional comments.

## 1. Block diagram:

The 2.402~2,480GHz frequency value of the XTAL shown on block diagram is not correct. 2.402~2,480GHz frequency is for operating frequency, but not the real value of the XTAL. The correct value of XTAL should be 16MHz according to the provided schematics. Please supply revised block diagram with correct frequency value.

## 2. Test report:

The antenna photo at page 8 of 48 is out of focus. Please provide a better photo.

George Chen Chief Technical Officer - Asia

## mailto:george@atcb.com

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.