
Photograph of the EUT 1.

EUT: WLAN/Bluetooth module (Hewlett-Packard / HSTNN-I77C)


Report No.: EP052502




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4

Page Number : 1 of 26 Report Issued Date : Jul. 28, 2010

Report Version : Rev. 02





EUT: WLAN/Bluetooth module (Hewlett-Packard / HSTNN-I77C)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 2 of 26
Report Issued Date : Jul. 28, 2010
Report Version : Rev. 02

2. External Photograph of the Host

Host: Notebook Computer (Hewlett-Packard / HSTNN-I77C)

Report No.: EP052502



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 3 of 26
Report Issued Date : Jul. 28, 2010
Report Version : Rev. 02

Report No.: EP052502



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 4 of 26
Report Issued Date : Jul. 28, 2010
Report Version : Rev. 02

Report No.: EP052502



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 5 of 26
Report Issued Date : Jul. 28, 2010
Report Version : Rev. 02

Report No.: EP052502



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 6 of 26
Report Issued Date : Jul. 28, 2010
Report Version : Rev. 02

Report No.: EP052502



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 7 of 26
Report Issued Date : Jul. 28, 2010
Report Version : Rev. 02

Report No.: EP052502



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 8 of 26
Report Issued Date : Jul. 28, 2010
Report Version : Rev. 02

Report No.: EP052502



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 9 of 26
Report Issued Date : Jul. 28, 2010
Report Version : Rev. 02

Report No.: EP052502



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 10 of 26
Report Issued Date : Jul. 28, 2010
Report Version : Rev. 02

3. Photograph of Accessory for the Host

Host: Notebook Computer (Hewlett-Packard / HSTNN-I77C)

Report No.: EP052502

List of Accessory for Host (Notebook Computer):

Specification of Accessory		
Brand Name HP		
AC Adapter 1	Manufacturer	Hipro (M5)
	Model Name	HP-OK065B13 8SELF
	Part Number	519329-002
	Part Number	I/P:100-240Vac, 50-60Hz, 1.7A;
	Power Rating	O/P: 18.5Vdc, 3.5A
AC Adapter 2	Brand Name	HP
	Manufacturer	Lite-On (LL)
	Model Name	PA-1650-32HN
	Part Number	519329-001
	Power Rating	I/P:100-240Vac, 50-60Hz, 1.6A; O/P: 18.5Vdc, 3.5A
AC Adapter 3	Brand Name	HP
	Manufacturer	Hipro (M5)
	Model Name	HP-OK065B13 8SELF
	Part Number	519329-002
	Power Rating	I/P:100-240Vac, 50-60Hz, 1.7A; O/P: 18.5Vdc, 3.5A
AC Adapter 4	Brand Name	HP
	Manufacturer	Lite-On (LL)
	Model Name	PA-1650-34HV
	Part Number	577051-001
	Power Rating	I/P:100-240Vac, 50-60Hz, 1.6A; O/P: 18.5Vdc, 3.5A
AC Adapter 5	Brand Name	HP
	Manufacturer	Hipro (M5)
	Model Name	HP-OK065B13 8SELF
	Part Number	519330-002
	Power Rating	I/P:100-240Vac, 50-60Hz, 1.5A; O/P: 19Vdc, 4.74A
	DC Power Cord Type	1.7 meter shielded cable with ferrite core
Battery	Brand Name	HP
	Manufacturer	Dynapack (TY)
	Model Name	LU06062
	Part Number	582215-241
	Power Rating	11.1Vdc, 62Wh
	Туре	Li-ion

Remark:

- 1. For accessories equipped with this EUT, please refer to the following photos.
- 2. Only the highest gain antenna (Antenna 1) and AC Adapter 5 was used for SAR testing.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 11 of 26
Report Issued Date : Jul. 28, 2010
Report Version : Rev. 02

Report No.: EP052502



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 12 of 26
Report Issued Date : Jul. 28, 2010
Report Version : Rev. 02

Report No.: EP052502




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 13 of 26
Report Issued Date : Jul. 28, 2010
Report Version : Rev. 02

Report No.: EP052502



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 14 of 26
Report Issued Date : Jul. 28, 2010
Report Version : Rev. 02





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 15 of 26
Report Issued Date : Jul. 28, 2010
Report Version : Rev. 02





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 16 of 26
Report Issued Date : Jul. 28, 2010
Report Version : Rev. 02

Report No.: EP052502



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 17 of 26 Report Issued Date : Jul. 28, 2010

Report Version : Rev. 02