FCC ID: VQF-RT5390

Description of Permissive Change

- 1. This report is prepared for FCC class II permissive change. The difference compared with the Report No.: RF130313E02E design is as the following information:
- Upgraded standard version.
- ◆ The Transfer of Control including all of the equipment currently authorized to the Ralink is affected; and that MediaTek Inc. assumes responsibility for the continued compliance of equipment marketed under the Ralink Technology Corp. Grantee Code.
- 2. According to above conditions, all test items need to be performed. And all data was verified to meet the requirements.

Reference no.: RF130313E02G