1. External Photograph of EUT

Brand Name: LG / Model Name: LGP43, P430, PB430, PD430, PV430

Report No.: EP140837



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 1 of 13 Report Issued Date : Apr. 27, 2011

Report Version : Rev. 01

Report No.: EP140837



Brand Name: LG / Model Name: LGP43, P430, PB430, PD430, PV430

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 2 of 13
Report Issued Date : Apr. 27, 2011
Report Version : Rev. 01



Brand Name: LG / Model Name: LGP43, P430, PB430, PD430, PV430

Report No.: EP140837



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4

Page Number : 3 of 13 Report Issued Date : Apr. 27, 2011 Report Version : Rev. 01

2. Photograph of Accessory

Brand Name: LG / Model Name: LGP43, P430, PB430, PD430, PV430

Report No.: EP140837

List of Accessory:

Specification of Accessory		
IAC Adanter	Brand Name	LG
	Model Name	PA-1900-08
Battery	Brand Name	LG
	Model Name	LB3211LK
WLAN Module	Brand Name	Ralink
	Model Name	RT3090BC4
Antenna 1	Brand Name	WNC
Antenna 2	Brand Name	WHAYU

Remark: For accessories equipped with this EUT, please refer to the following photos.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 4 of 13
Report Issued Date : Apr. 27, 2011
Report Version : Rev. 01

Report No.: EP140837



Brand Name: LG / Model Name: LGP43, P430, PB430, PD430, PV430

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4

Page Number : 5 of 13 Report Issued Date : Apr. 27, 2011

Report Version : Rev. 01 Brand Name: LG / Model Name: LGP43, P430, PB430, PD430, PV430

Report No.: EP140837



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 6 of 13
Report Issued Date : Apr. 27, 2011
Report Version : Rev. 01

Brand Name: LG / Model Name: LGP43, P430, PB430, PD430, PV430

Report No.: EP140837



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : 7 of 13
Report Issued Date : Apr. 27, 2011
Report Version : Rev. 01