
1. Photograph of the EUT

EUT: 802.11 b/g/n 1T1R WLAN MINI card (Brand Name: Ralink / Model Name: RT3290)




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 1 of 25

Report No.: EP3D1372-03

Report Issued Date : Jan. 21, 2014 Report Version : Rev. 01


Report No.: EP3D1372-03

EUT: 802.11 b/g/n 1T1R WLAN MINI card (Brand Name: Ralink / Model Name: RT3290)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 2 of 25
Report Issued Date : Jan. 21, 2014
Report Version : Rev. 01


EUT: 802.11 b/g/n 1T1R WLAN MINI card (Brand Name: Ralink / Model Name: RT3290)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 3 of 25
Report Issued Date : Jan. 21, 2014
Report Version : Rev. 01

Report No.: EP3D1372-03

EUT: 802.11 b/g/n 1T1R WLAN MINI card (Brand Name: Ralink / Model Name: RT3290)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 4 of 25
Report Issued Date : Jan. 21, 2014
Report Version : Rev. 01

2. External Photograph of the Host

Host: Notebook PC (Brand Name: Hewlett-Packard / Model Name: TPN-C115)

Report No.: EP3D1372-03



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 5 of 25
Report Issued Date : Jan. 21, 2014
Report Version : Rev. 01

Report No.: EP3D1372-03



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 6 of 25
Report Issued Date : Jan. 21, 2014
Report Version : Rev. 01

Report No.: EP3D1372-03



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 7 of 25
Report Issued Date : Jan. 21, 2014
Report Version : Rev. 01

Report No.: EP3D1372-03



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 8 of 25
Report Issued Date : Jan. 21, 2014
Report Version : Rev. 01

Report No.: EP3D1372-03



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 9 of 25
Report Issued Date : Jan. 21, 2014
Report Version : Rev. 01



Report No.: EP3D1372-03



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290

Page Number : 10 of 25 Report Issued Date : Jan. 21, 2014 Report Version : Rev. 01

3. Photograph of Accessory for the Host

Host: Notebook PC (Brand Name: Hewlett-Packard / Model Name: TPN-C115)

Report No.: EP3D1372-03


List of Accessory for Host (Notebook PC):

.,		
Specification of Accessory		
Battery 1	Brand Name	HP
	Model Name	HSTNN-DB6B
IBattery 2	Brand Name	HP
	Model Name	HSTNN-LB6B

Remark: For accessories equipped with this EUT, please refer to the following photos.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 11 of 25
Report Issued Date : Jan. 21, 2014
Report Version : Rev. 01

Report No.: EP3D1372-03



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290

Page Number : 12 of 25 Report Issued Date : Jan. 21, 2014

Report Version : Rev. 01

Report No.: EP3D1372-03

PACK ENGINEERING SAM PL02029XL samples for development phase qualification

Supplier: Dynapack RMN No.: HSTNN-DB6B HP PN: 751681-231 Q-Matrix ID:116926

Gas Gauge IC: BQ30Z55,FW:Ver.0.36 H/W: Ver.1.0 EEPROM:Ver.1.0

Connector: ACES

Cell:Panasonic NCA596080 4.18A

Stage: SI Voltage: 7.2V Capacity: 2S1P/29Wh

Date: 131101-290

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290

Page Number : 13 of 25

Report Issued Date : Jan. 21, 2014

: Rev. 01 Report Version


Report No.: EP3D1372-03



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 14 of 25
Report Issued Date : Jan. 21, 2014
Report Version : Rev. 01



Report No.: EP3D1372-03



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290

Page Number : 15 of 25 Report Issued Date : Jan. 21, 2014 Report Version : Rev. 01

Report No.: EP3D1372-03



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 16 of 25
Report Issued Date : Jan. 21, 2014
Report Version : Rev. 01

Report No.: EP3D1372-03

Phelps SI ever

Q-Matrix ID: 116927 LG P/N: HP011309-PRR12G01

HP PJT P/N: HSTNN-LB6B

HW/F/W/EEProm: A01/0.36/131016

Manufacture Date: 2013/10/30 HP P/N:751681-421

-001 date 113/10 Model: PL02029XL Supplier: LGC

Cell type: ICP606080L1 Rating voltage/Wh:7.6V/29Wh

Connector type: ACES Phase: SI sample

2nd IC : SEIKO C/D FET :AOS

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290

Page Number

: 17 of 25

Report Issued Date : Jan. 21, 2014

: Rev. 01 Report Version

Report No.: EP3D1372-03



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290

Page Number

: 18 of 25 Report Issued Date : Jan. 21, 2014


Report Version

: Rev. 01





Report No.: EP3D1372-03



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290

Page Number : 19 of 25 Report Issued Date : Jan. 21, 2014 Report Version : Rev. 01