


Report No.: FA151308

Appendix D. Product Photos




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 Page Number : D1 of D1 Report Issued Date: Jun. 10, 2011 Report Version : Rev. 01



Appendix E. Test Setup Photos



Bottom of the DUT with Phantom 0 cm Gap

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 Page Number : E1 of E1 Report Issued Date: Jun. 10, 2011

Report No. : FA151308

Report Version : Rev. 01