
1. Photograph of the EUT

EUT: WLAN module (Brand Name: Ralink / Model Name: RT3290)

Report No.: EP112725-17



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 1 of 20
Report Issued Date : Jun. 24, 2013
Report Version : Rev. 01



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 2 of 20
Report Issued Date : Jun. 24, 2013
Report Version : Rev. 01

2. External Photograph of the Host

Host: Notebook PC (Brand Name: hp / Model Name: TPN-Q133)

Report No.: EP2D0508-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 3 of 20
Report Issued Date : Jun. 24, 2013
Report Version : Rev. 01

Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 4 of 20
Report Issued Date : Jun. 24, 2013
Report Version : Rev. 01

Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290

Page Number : 5 of 20 Report Issued Date : Jun. 24, 2013

Report Version : Rev. 01

3. Photograph of Accessory for the Host

Host: Notebook PC (Brand Name: hp / Model Name: TPN-Q133)

Report No.: EP2D0508-01

List of Accessory for Host (Notebook PC):

and the state of		
Specification of Accessory		
AC Adapter	Brand Name	hp
	Model Name	HSTNN-LA35
Battery	Brand Name	hp
	Model Name	WO03XL
Keyboard Battery	Brand Name	hp
	Model Name	WR03XL
Keyboard	Brand Name	hp
	Model Name	N/A

Remark: For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 6 of 20
Report Issued Date : Jun. 24, 2013
Report Version : Rev. 01

Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 7 of 20
Report Issued Date : Jun. 24, 2013
Report Version : Rev. 01

Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 8 of 20
Report Issued Date : Jun. 24, 2013
Report Version : Rev. 01



Battery

| Comparison of the Comparison of Control Con

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 9 of 20
Report Issued Date : Jun. 24, 2013
Report Version : Rev. 01

Report No.: EP2D0508-01

Report No.: EP2D0508-01

311KR00015 A01



European Regulatory Address: HP, HQ-TRE, 71004 Boeblingen, Germany, HP is a registered trademark of Hewlett-Packard Company HP part number 725496-1B1

FOR USE WITH HP SERIES HSTNN-XXXX FAMILY COMPUTER PRODUCTS ONLY REGULATORY MODEL NUMBER HSTNN-IB5I 系列 电芯原产地中国并于中国加工组装 CELL ORIGIN CHINA FURTHER PROCESSED IN CHINA



To reduce risk of fire or burns, do not disassemble, crush, or puncture; do not short external contact; do not dispose of in fire or water.

警告! 为避免引起火灾或燃烧,请勿拆卸、挤压、刺戳电池,或使电池外部接点短路; 请不要将电池抛入到火中或水中 警告! 爲避免引起火災或燃燒,請勿拆卸、擠壓、刺戳電池,或使電池外部接點短路;請不要將電池拋入到火中或水中

11.1V == 33Wh

STCS-CHA-LISHEN

STORE BETWEEN 0°C TO 60°C | 32°F TO 140°F 储藏温度范围

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290

Page Number


: 10 of 20

Report Issued Date : Jun. 24, 2013

Report Version

: Rev. 01

otographs of EUT Report No.: EP2D0508-01



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 11 of 20
Report Issued Date : Jun. 24, 2013

Report Version : Rev. 01

Report No.: EP2D0508-01



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 12 of 20
Report Issued Date : Jun. 24, 2013
Report Version : Rev. 01

Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 13 of 20
Report Issued Date : Jun. 24, 2013
Report Version : Rev. 01

Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 14 of 20
Report Issued Date : Jun. 24, 2013
Report Version : Rev. 01

Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 15 of 20
Report Issued Date : Jun. 24, 2013
Report Version : Rev. 01

Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3290 IC: 7542A-RT3290 Page Number : 16 of 20
Report Issued Date : Jun. 24, 2013
Report Version : Rev. 01