



Setup Photographs

<Conducted Emission>



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : B1 of B4
Report Issued Date : Jun. 21, 2010
Report Version : Rev. 01

Report No.: FR052502B





Report No.: FR052502B

Side View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4

: B2 of B4 Page Number Report Issued Date: Jun. 21, 2010

Report Version : Rev. 01




Report No. : FR052502B

<Radiated Emission>



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : B3 of B4
Report Issued Date : Jun. 21, 2010
Report Version : Rev. 01



Report No.: FR052502B



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQF-RT3090BC4 IC: 7542A-RT3090BC4 Page Number : B4 of B4
Report Issued Date : Jun. 21, 2010
Report Version : Rev. 01