


Date: Jan 16, 2008 Report No.: RY0801P16R2

Model: F884i

## 3 Test setup photographs



Temperature test (Frequency Stability)



AC Line Conducted emission

Page 53 of 58

**RF Technologies Ltd.**472, Nippa-cho, Kohoku-ku, Yokohama, 223-0057, Japan
Telephone: +81+(0)45- 534-0645, FAX: +81+(0)45- 534-0646, Web: http://www.rft.jp



Date: Jan 16, 2008 Report No.: RY0801P16R2 Model: F884i



Radiated emission 1

**RF Technologies Ltd.**472, Nippa-cho, Kohoku-ku, Yokohama, 223-0057, Japan
Telephone: +81+(0)45- 534-0645, FAX: +81+(0)45- 534-0646, Web: http://www.rft.jp



Date: Jan 16, 2008 Report No.: RY0801P16R2 Model: F884i



Radiated Emission 2



Radiated Emission 3

**RF Technologies Ltd.**472, Nippa-cho, Kohoku-ku, Yokohama, 223-0057, Japan
Telephone: +81+(0)45- 534-0645, FAX: +81+(0)45- 534-0646, Web: http://www.rft.jp