


Report No. : FA370119


Appendix D. SAR Test Setup Photos






Right Cheek

Right Tilted





Left Cheek

Left Tilted

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQK-F01F

Page Number : D1 of D2 Report Issued Date: Sep. 06, 2013 : Rev. 01


Report Version







Front, Test Separation 1 cm



Report No.: FA370119

Back, Test Separation 1 cm



Bottom Side, Test Separation 1 cm



Top Side, Test Separation 1 cm



Right Side, Test Separation 1 cm



Left Side, Test Separation 1 cm

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQK-F01F

Page Number : D2 of D2 Report Issued Date: Sep. 06, 2013 Report Version : Rev. 01