Test Photos Report No. : FR322231AC

Appendix A. TEST PHOTOS

1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A1 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01



rest Photos Report No. : FR322231AC



SIDE VIEW


SPORTON INTERNATIONAL INC. Page No. : A2 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01

Test Photos Report No. : FR322231AC

2 Photographs of Radiated Emissions Test Configuration For radiated emission below 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01

Test Photos Report No. : FR322231AC

For radiated emission above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A4 of A4 TEL: 886-3-327-3456 Report Version : Rev. 01