

Report No.: FA391345

Appendix D. SAR Test Setup Photos





Right Cheek

Right Tilted





Left Cheek Left Tilted

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQK-F03F Page Number : D1 of D2
Report Issued Date : Oct. 25, 2013

Report Version : Rev. 01







nuluuluuluu

Front, Test Separation 1 cm



Report No.: FA391345








Top Side, Test Separation 1 cm







Left Side, Test Separation 1 cm

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQK-F03F

Page Number : D2 of D2 Report Issued Date: Oct. 25, 2013 Report Version : Rev. 01