

Date: 16 Feb, 2010 Report No.: RY1002P16R1

Model: F-07B

## 3 Test setup photographs



Temperature test (Frequency stability)

RF Technologies Ltd. Page 33 of 34

472, Nippa-cho, Kohoku-ku, Yokohama, 223-0057, Japan Telephone: +81+(0)45- 534-0645, FAX: +81+(0)45- 534-0646, Web: http://www.rft.jp