



Report No.: FA331935

Appendix D. SAR Test Setup Photos



Right Cheek


Right Tilted





Left Cheek

Left Tilted





Front, Test Separation 1 cm




Back, Test Separation 1cm

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQK-F07E

Page Number : D1 of D2 Report Issued Date: May 31, 2013 Report Version : Rev. 01






Top Side, Test Separation 1 cm




Report No.: FA331935

Bottom Side, Test Separation 1 cm



Left Side, Test Separation 1 cm



Right Side, Test Separation 1 cm

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQK-F07E

Page Number : D2 of D2 Report Issued Date: May 31, 2013

Report Version : Rev. 01