


Date: Oct 17, 2008 Report No.: RY0810P17R6

Model: F-06A

3 Test setup photographs



AC Line Conducted emission

472, Nippa-cho, Kohoku-ku, Yokohama, 223-0057, Japan Telephone: +81+(0)45- 534-0645, FAX: +81+(0)45- 534-0646, Web: http://www.rft.jp



Date: Oct 17, 2008 Report No.: RY0810P17R6 Model: F-06A



Radiated emission 1



Radiated emission 2


RF Technologies Ltd.472, Nippa-cho, Kohoku-ku, Yokohama, 223-0057, Japan
Telephone: +81+(0)45- 534-0645, FAX: +81+(0)45- 534-0646, Web: http://www.rft.jp



Date: Oct 17, 2008 Report No.: RY0810P17R6 Model: F-06A



Radiated Emission 3



Radiated Emission 4

RF Technologies Ltd.472, Nippa-cho, Kohoku-ku, Yokohama, 223-0057, Japan
Telephone: +81+(0)45- 534-0645, FAX: +81+(0)45- 534-0646, Web: http://www.rft.jp