

Date: 07 Jul, 2010

Report No.: RY1007P07R2

Model: F-10B

3 Test setup photographs



Temperature test (Frequency stability)

RF Technologies Ltd. Page 33 of 34

472, Nippa-cho, Kohoku-ku, Yokohama, 223-0057, Japan Telephone: +81+(0)45- 534-0645, FAX: +81+(0)45- 534-0646, Web: http://www.rft.jp