

Date: Aug 13, 2008 Report No.: RY0808P13R2

Model: F-01A

3 Test setup photographs



Temperature test (Frequency Stability)



AC Line Conducted emission

Page 42 of 46

RF Technologies Ltd.472, Nippa-cho, Kohoku-ku, Yokohama, 223-0057, Japan
Telephone: +81+(0)45- 534-0645, FAX: +81+(0)45- 534-0646, Web: http://www.rft.jp



Date: Aug 13, 2008 Report No.: RY0808P13R2 Model: F-01A



Radiated emission 1




Radiated emission 2

RF Technologies Ltd.472, Nippa-cho, Kohoku-ku, Yokohama, 223-0057, Japan
Telephone: +81+(0)45- 534-0645, FAX: +81+(0)45- 534-0646, Web: http://www.rft.jp



Date: Aug 13, 2008 Report No.: RY0808P13R2 Model: F-01A



Radiated Emission 3



Radiated Emission 4

RF Technologies Ltd.472, Nippa-cho, Kohoku-ku, Yokohama, 223-0057, Japan
Telephone: +81+(0)45- 534-0645, FAX: +81+(0)45- 534-0646, Web: http://www.rft.jp