

Date: Oct. 03, 2008 Report No.: RY0810P03R1 Model: F-02A

## 3 Test setup photographs



Temperature test (Frequency Stability)



AC Power Line emission

Page 42 of 46 RF Technologies Ltd.

472, Nippa-cho, Kohoku-ku, Yokohama, 223-0057, Japan Telephone: +81+(0)45- 534-0645, FAX: +81+(0)45- 534-0646, Web: http://www.rft.jp



Date: Oct. 03, 2008 Report No.: RY0810P03R1 Model: F-02A



Radiated emission 1



Radiated emission 2


**RF Technologies Ltd.**472, Nippa-cho, Kohoku-ku, Yokohama, 223-0057, Japan
Telephone: +81+(0)45- 534-0645, FAX: +81+(0)45- 534-0646, Web: http://www.rft.jp



Date: Oct. 03, 2008 Report No.: RY0810P03R1 Model: F-02A



Radiated Emission 3



Radiated Emission 4

**RF Technologies Ltd.**472, Nippa-cho, Kohoku-ku, Yokohama, 223-0057, Japan
Telephone: +81+(0)45- 534-0645, FAX: +81+(0)45- 534-0646, Web: http://www.rft.jp