
Test Photos Report No. : FR322231

Appendix A. TEST PHOTOS

1 Photographs of Radiated Emissions Test Configuration For radiated emission 9K~30MHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A1 of A2 TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973

Test Photos Report No. : FR322231

For radiated emission 30MHz~1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A2 TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973