

Date: 23 Aug, 2010 Report No.: RY1008P23R1 Model: F-02C

3 Test setup photographs



Temperature test (Frequency stability)

Page 24 of 25 RF Technologies Ltd.

472, Nippa-cho, Kohoku-ku, Yokohama, 223-0057, Japan Telephone: +81+(0)45- 534-0645, FAX: +81+(0)45- 534-0646, Web: http://www.rft.jp