



Appendix D. Product Photos



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQK-F07D Page Number : D1 of D2
Report Issued Date : Nov. 18, 2011
Report Version : Rev. 02

Report No.: FA190323





Antenna location	Length	Width
WWAN Antenna <tx rx=""></tx>	5.3cm	0.4cm
Bluetooth & WLAN Antenna <tx rx=""></tx>	1.1cm	0.3cm
RFID Antenna <tx rx=""></tx>	3.7cm	3.0cm
GPS Antenna <rx></rx>	1.6cm	0.4cm


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQK-F07D Page Number : D2 of D2
Report Issued Date : Nov. 18, 2011
Report Version : Rev. 02

Report No.: FA190323



Report No. : FA190323


Appendix E. Test Setup Photos





Right Cheek


Right Tilted







Left Cheek

Left Tilted








Front of the DUT with Phantom 1 cm Gap (DUT without Earphone)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQK-F07D Page Number : E1 of E2
Report Issued Date : Nov. 18, 2011
Report Version : Rev. 02




Back of the DUT with Phantom 1 cm Gap (DUT with Earphone)




Report No.: FA190323


Back of the DUT with Phantom 1 cm Gap (DUT without Earphone)




Right Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQK-F07D Page Number : E2 of E2
Report Issued Date : Nov. 18, 2011
Report Version : Rev. 02