Test Photos Report No. : FR322231AN

## **Appendix A. TEST PHOTOS**

## 1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A1 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01



Test Photos Report No. : FR322231AN



SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01



2 Photographs of Radiated Emissions Test Configuration For radiated emission 9K~30MHz



Report No.: FR322231AN

FRONT VIEW



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A3 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01

est Photos Report No. : FR322231AN

## For radiated emission 30MHz~1GHz



FRONT VIEW



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A4 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01