

Report No.: FA3D2624

## Appendix D. SAR Test Setup Photos





**Right Cheek** 

**Right Tilted** 





Left Cheek Left Tilted

 SPORTON INTERNATIONAL INC.
 Page D1 of D2
 Issued Date
 : Mar. 20, 2014


 TEL: 886-3-327-3456 / FAX: 886-3-328-4978
 Form version.
 : FAA140305

FCC ID : VQK-F05F





Front, Test Separation 1 cm



Back, Test Separation 1 cm



**Bottom Side, Test Separation 1 cm** 



**Top Side, Test Separation 1 cm** 



Right Side, Test Separation 1 cm



Left Side, Test Separation 1 cm

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 / FAX: 886-3-328-4978

FCC ID: VQK-F05F

Page D2 of D2

Issued Date

: Mar. 20, 2014

Form version.

: FAA140305