


Report No.: FR190323A

Appendix B. Setup Photographs

<Conducted Emission>




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQK-F07D Page Number : B1 of B2
Report Issued Date : Nov. 17, 2011
Report Version : Rev. 01



<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VQK-F07D Page Number : B2 of B2
Report Issued Date : Nov. 17, 2011
Report Version : Rev. 01

Report No.: FR190323A