


Date: 17 Feb, 2010 Report No.: RY1002P17R2 Model: F-08B

3 Test setup photographs



Temperature test (Frequency stability)

Page 33 of 34 RF Technologies Ltd.

472, Nippa-cho, Kohoku-ku, Yokohama, 223-0057, Japan Telephone: +81+(0)45- 534-0645, FAX: +81+(0)45- 534-0646, Web: http://www.rft.jp