


# Appendix D. Setup Photographs

## <Conducted Emission>

#### Mode 1



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: VQRCTX818 Page Number : D1 of D2
Report Issued Date : Dec. 06, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.3


Report No.: FR6O2403C




### <Radiated Emission>

#### X Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: VQRCTX818 Page Number : D2 of D2
Report Issued Date : Dec. 06, 2016
Report Version : Rev. 01

Report No.: FR6O2403C

Report Template No.: BU5-FR15CWL Version 1.3