



## Appendix B. Setup Photographs

## <Conducted Emission>

Mode 1



Front View



Rear View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: VQRCTX830 Page Number : B1 of B4
Report Issued Date : Aug. 04, 2010
Report Version : Rev. 01

Report No.: FR061722





Report No.: FR061722



Side View


SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: VQRCTX830 Page Number : B2 of B4
Report Issued Date : Aug. 04, 2010
Report Version : Rev. 01





## <Radiated Emission>



Front View



Rear View

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: VQRCTX830 Page Number : B3 of B4
Report Issued Date : Aug. 04, 2010
Report Version : Rev. 01

**Report No.: FR061722** 





Report No.: FR061722



Remote View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: VQRCTX830 Page Number : B4 of B4
Report Issued Date : Aug. 04, 2010
Report Version : Rev. 01