
3. Internal Photograph of EUT

Brand Name: Philips / Model Name: X830

Report No.: EP061722



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: VQRCTX830 Page Number : 18 of 23
Report Issued Date : Aug. 04, 2010
Report Version : Rev. 01





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: VQRCTX830 Page Number : 19 of 23
Report Issued Date : Aug. 04, 2010
Report Version : Rev. 01

Report No.: EP061722



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: VQRCTX830 Page Number : 20 of 23
Report Issued Date : Aug. 04, 2010
Report Version : Rev. 01

Report No.: EP061722



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: VQRCTX830 Page Number : 21 of 23
Report Issued Date : Aug. 04, 2010
Report Version : Rev. 01

Report No.: EP061722



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: VQRCTX830 Page Number : 22 of 23
Report Issued Date : Aug. 04, 2010
Report Version : Rev. 01

Report No.: EP061722



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: VQRCTX830 Page Number : 23 of 23
Report Issued Date : Aug. 04, 2010
Report Version : Rev. 01