3. Internal Photograph of EUT

Brand Name: Philips / Model Name: X603

Report No.: EP070835



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: VQRCTX603 Page Number : 18 of 25
Report Issued Date : Jul. 27, 2010
Report Version : Rev. 01

Report No.: EP070835



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: VQRCTX603 Page Number : 19 of 25
Report Issued Date : Jul. 27, 2010
Report Version : Rev. 01

Report No.: EP070835



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: VQRCTX603 Page Number : 20 of 25
Report Issued Date : Jul. 27, 2010
Report Version : Rev. 01

Report No.: EP070835



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: VQRCTX603 Page Number : 21 of 25
Report Issued Date : Jul. 27, 2010
Report Version : Rev. 01

Report No.: EP070835




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: VQRCTX603 Page Number : 22 of 25
Report Issued Date : Jul. 27, 2010
Report Version : Rev. 01

Report No.: EP070835




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: VQRCTX603 Page Number : 23 of 25
Report Issued Date : Jul. 27, 2010
Report Version : Rev. 01

Report No.: EP070835



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: VQRCTX603 Page Number : 24 of 25
Report Issued Date : Jul. 27, 2010
Report Version : Rev. 01

Report No.: EP070835



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: VQRCTX603

Page Number : 25 of 25 Report Issued Date : Jul. 27, 2010 Report Version : Rev. 01