

Report No.: FA061722

Appendix D. Product Photos





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: VQRCTX830 Page Number : D1 of D1
Report Issued Date : Aug. 04, 2010
Report Version : Rev. 01



Report No.: FA061722

Appendix E. **Test Setup Photos**




Right Cheek



Left Cheek



Left Tilted



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: VQRCTX830

Page Number : E1 of E1 Report Issued Date: Aug. 04, 2010 Report Version : Rev. 01