

Report No.: F-R0911001 Page 23 of 29







Photo 4





Report No.: F-R0911001 Page 24 of 29







Photo 6





Report No.: F-R0911001 Page 25 of 29

FCCID: VQXAEC9336CU

## Photo 7





Photo 8





Report No.: F-R0911001 Page 26 of 29

Photo 9




Photo 10






Report No.: F-R0911001 Page 27 of 29





Photo 12





Report No.: F-R0911001 Page 28 of 29

Photo 13





Photo 14





Report No.: F-R0911001 Page 29 of 29

FCCID: VQXAEC9336CU

## Photo 15

