

1132 West 1700 North Logan, UT 84321 USA t.435.753.1881 f.435.753.1896 js@junipersys.com www.junipersys.com

September 12, 2013

Federal Communications Commission Equipment Authorization Branch 7435 Oakland Mills Road Columbia, MD 21046

Re: Part 2.933 Change in Identification to FCC ID: VSF23545

Dear Sir or Madam,

I hereby request a change in identification in accordance to CFR 47 Part 2.933 of the FCC rules. The original identification used on the equipment prior to this application for Change in Identification is TFB-TIWI1-01. The date of the original grant of the equipment authorization is 12/10/2010.

I hereby certify that the equipment bearing the modified identification, FCC ID: VSF23545, does not differ from the original equipment.

I further certify that the original test results continue to be representative of and applicable to the equipment bearing the changed identification.

Sincerely,

Kent Campbell

Product Assurance Engineer