

1132 West 1700 North t.435.753.1881 Logan, UT 84321 USA f.435.753.1896

js@junipersys.com www.junipersys.com

Subject: Request to change in Identification.

Dear Regulatory Authority,

This Change of Identification request applies for a new FCC ID: as established in 47CFR 2.933(b) for a currently approved device. This application by Juniper Systems, Inc. will establish a new FCC ID: VSF22779 under Juniper Systems, Inc. grantee code for purpose of marketing. The original grant to Multi Tech Systems will remain in effect.

Per 2.933(b)

- 1. The original identification is AU792U09G17826
- 2. The original grant date is 10/22/2009
- 3. The equipment is electrically identical. Only the model name, trade name, and FCC ID number are different.
- 4. The original test results are applicable and representative of this changed device.
- 5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter

External Photos

FCC ID label format and location

Sincerely,

Kent Campbell

Product Assurance Manager

Juniper Systems, Inc.