Report Number: 07-0269


Issue Date: April 14, 2008

Customer: World Office Products

Model #: F238250 F250 / F238

FCC ID: VSK-F250F238

5.3 EUT, Bottom View, Cover Removed, Transmitter and Digital Boards Solder Side



Report Number: 07-0269


Issue Date: April 14, 2008

Customer: World Office Products


Model #: F238250 F250 / F238

FCC ID: VSK-F250F238

5.4 EUT, Transmitter and Digital boards Component Side



5.5 EUT, Sensor Cover Removed



Report Number: 07-0269


Issue Date: April 14, 2008

Customer: World Office Products

Model #: F238250 F250 / F238

FCC ID: VSK-F250F238

5.6 EUT, Sensor boards Component Side



Report Number: 07-0269

Issue Date: April 14, 2008

Customer: World Office Products

Model #: F238250 F250 / F238

FCC ID: VSK-F250F238

Photo 7. EUT, Sensor boards Solder Side

